


## Vicinity Map

Uncompangre River Stabilization & Recreation Improvements

Riverbend Engineering 140A Solomon Dr. Pagosa Springs, CO 81147 tel: 970-731-0065 Fax: 907-731-0264 e-mail: cphilips@frontier.net


Scale: 1" = 2000 ft




Uncompangre River Stabilization & Recreation Improvements

## Riverbend Engineering 140A Solomon Dr. Pagosa Springs, CO 81147 tel: 970-731-0065 Fax: 907-731-0264 e-mail: cphilips@frontier.net

Scale: 1" = 50 ft



Scale: 1" = 20 ft



# Structure Longitudinal Profile

Uncompangre River Stabilization & Recreation Improvements

Riverbend Engineering 140A Solomon Dr. Pagosa Springs, CO 81147 tel: 970-731-0065 Fax: 907-731-0264 e-mail: cphilips@frontier.net

Scale: Not to Scale

## Project Quantities Updated 1-18-06

### Grade Stabilization and Whitewater Structure No. 2:

#### Below OHWM:

Large Boulders, approximately 60 EA, or 75 CY
Medium Rock, approximately 40 CY
Concrete, used as grout between boulders, approximately 60 CY
Alluvial fill, shaping of channel subgrade, approximately 110 CY
Above OHWM:

Large Boulders, approximately 40 EA, or 50 CY Concrete, used as grout between boulders, **NONE** Alluvial fill, shaping of channel sideslopes, approximately 160 CY Willow transplants between boulders, approximately 40 dormant plants


#### Notes:

- 1) Exposed concrete surface area is approximately 500 sq ft. The sloping ramp area is nominally 50 ft wide, by 40 ft long (net of 2000 sq ft), and the concrete grout comprises approximately 25% of the surface area.
- 2) Alluvial fill obtained from in-stream sediment deposit, just downstream of work area
- 3) The willow transplant work is expected to be completed in late winter, while the plants are still dormant

### PROPOSED Cross Vane Structure Downstream, Drop #3:

Large Boulders, approximately 60 EA, or 75 CY Alluvial fill, shaping of channel subgrade, approximately 100 CY

NOTE: Quantities shown in Block 21 of application form 4345 are incorrect. Please cross out that text and refer to this attachment. Thank you.




#### **OVERAI** PROFIL PROPOSED

Uncompangre River Stabilization & Recreation Improvements

Riverbend Engineering
140A Solomon Dr. Pagosa Springs, CO 81147
tel: 970-731-0065 Fax: 907-731-0264
e-mail: cphilips@frontier.net

Scale: 1" = 50 ft

1-18-06





### Structure Cross Section

Uncompangre River Stabilization & Recreation Improvements

Riverbend Engineering
140A Solomon Dr. Pagosa Springs, CO 81147
tel: 970-731-0065 Fax: 907-731-0264
e-mail: cphilips@frontier.net

Scale: Not to Scale





# PROPOSED CROSS VANE DETAILS, Structure #3

Uncompangre River Stabilization & Recreation Improvements

Riverbend Engineering 140A Solomon Dr. Pagosa Springs, CO 81147 tel: 970-731-0065 Fax: 907-731-0264 e-mail: cphilips@frontier.net

Scale: 1" = 20 ft

1-18-06



Uncompangre River at Ridgway. First restoration design of upper reach, Fall 2002




Uncompangre River at Ridgway. Failure of first restoration design, Spring 2003 (showing remedial placement of rock to minimize bank cutting)



Uncompange River at Ridgway. Construction of Second design & lining of bed and banks with rock. Fall 2003



Uncompangre River at Ridgway, CO. Second design, post construction, Fall 2003




Uncompanded River at Ridgway. Third design, grade stabilization and whitewater structure No. 1, post construction; placement of pedestrian bridge, Spring 2005.

-Hwy bridge new pedestrian bridge

. Hwy bridge





Uncompangre River in Ridgway. Views of first structure from pedestrian bridge # 1



Uncompangre River in Ridgway View of second structure from west bank



Uncompangre River in Ridgway View of second structure from east bank メ 2